

MAXIMUS-3



JK WRANGLER


Side-Shooter/Cube Light Brackets

PART #: JK6003CL

INSTALLATION GUIDES

PLEASE MAKE SURE YOU READ AND UNDERSTAND THE ENTIRE INSTALLATION GUIDE BEFORE YOU START. WE EXPECT YOU TO HAVE BASIC MECHANICAL ABILITIES TO PERFORM THIS INSTALLATION.

WE RECOMMEND THAT YOU SEPARATE AND IDENTIFY ALL THE PARTS AND HARDWARE KITS YOU RECEIVED WITH YOUR SHIPMENT BEFORE YOU PROCEED TO DISASSEMBLE YOUR JEEP.



IMPORTANT

Follow these instructions precisely. Maximus-3 is not liable for any damage caused by improperly installed products. It is the purchaser's responsibility to ensure both the installation and maintenance are performed properly as set forth in this guide. We recommend using anti-size paste on all non-thread lock bolts.

Component List:


Cube Light Brackets Set

Qty

1

Tools Required:10MM Socket/Wrench
6MM Allen Key**INSTALLATION STEPS:**

1. Using M10 wrench/socket, remove the factory fender bolts pointed with arrows in the picture below.
2. Align your Maximus-3 Light Bracket to the holes and bolt down using the factory bolt and supplied hardware as shown below.
3. Bolt your Lights to the bracket as shown and route the wiring under the bracket and under the hood as desired, then connect to your Auxiliary Accessories wiring or wire following wiring instructions supplied with your lights. Use cable tie loops to secure the wire to bracket.
4. Repeat on the other side.





Your installation is complete. If you have questions regarding this installation, please contact us at sales@maximus-3.com or call 248 821 6654.